

Date of Issue: 03/29/2012 06:03:32  
DEP Bureau Of Laboratories - Harrisburg  
P.O. Box 1467  
2575 Interstate Drive  
Harrisburg, PA 17105-1467

PAGE 1 of 2

Contact Phone Number: (717) 346-7200

Analytical Report FOR  
Water Supply Management

Sample ID: 1208 417

Status: Completed

Name of Sample Collector: Stephen Brokenshire  
Date Sample was Collected: 01/23/2012

County: Susquehanna  
Municipality: Dimock Twp

State: PA

---

**Ex. 6 - Personal Privacy**

---

Sample Medium :  
Sample Medium Type:

Location: Kitchen Sink  
Reason: Project

Laboratory Sample ID: B2012000448  
Standard Analysis: B001

Completed

No treatment on system. Well cap unsecured. Two large piles of used asphalt were piled next to the drinking water well head.

Appearance: Clear

Test Codes/CAS# - Description Test Method	Reported Results	Date And Time Analyzed	Analyst
----- 31751 HETERO PLATE 9215B	33 /ML	01/24/2012 10:15 AM	MCHROSCINSSM
31501 COLIFORM FIL 9222B	<1 /100ML	01/24/2012 08:54 AM	MCHROSCINSSM
PAFC FCOL - PA 9221E		01/24/2012 08:54 AM	MCHROSCINSSM
** Comment **	ABSENT		

PAGE 1 of 2

Analytical Report FOR  
Water Supply Management

Sample ID: 1208 417

Status: Completed

\*\*\*\*\*  
\*\*\*\*\*  
The results of the analyses provided in this laboratory report relate only to the sample(s) identified in the report. Unless otherwise noted, the results presented on this laboratory report meet all the requirements of The NELAC Institute (TNI). Sample was in acceptable condition when received by the Laboratory. Any exceptions are noted in the report. Tests noted with an "\*" are not included in our NJ NELAP Annual Certified Parameter List.

Taru Upadhyay, Technical Director, Bureau of Laboratories

\*\*\*\*\*  
\*\*\*\*\*